

# Part 573 Safety Recall Report

# 22V-457

**Manufacturer Name :** Nissan North America, Inc.**Submission Date :** JUN 24, 2022**NHTSA Recall No. :** 22V-457**Manufacturer Recall No. :** R22A2 R22A3**Manufacturer Information :****Population :**

Manufacturer Name : Nissan North America, Inc.

Number of potentially involved : 180,176

Address : P. O. BOX685001

Estimated percentage with defect : 1 %

Franklin TN 37068-5009

Company phone : 800-647-7261

**Vehicle Information :**

Vehicle 1 : 2020-2021 Nissan Frontier

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : This issue is specific to Nissan Titan and Frontier vehicles equipped with 9-speed transmissions. No other Nissan or INFINITI vehicles are affected.

Production Dates : JUN 10, 2020 - JUN 25, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2022-2022 Nissan Frontier

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : This issue is specific to Nissan Titan and Frontier vehicles equipped with 9-speed transmissions. No other Nissan or INFINITI vehicles are affected.

Production Dates : JUL 13, 2021 - JUN 14, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2020-2022 Nissan Titan

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : This issue is specific to Nissan Titan and Frontier vehicles equipped with 9-speed transmissions. No other Nissan or INFINITI vehicles are affected.

Production Dates : DEC 13, 2019 - JUN 10, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

**Description of Defect :**

Description of the Defect : Due to dimensional variation during the manufacturing process, reduced clearance may cause contact between the edge of the parking pawl and the boss on the transmission case, which may result in non-engagement of the parking pawl.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If this occurs, an affected vehicle may move after placing the shifter into 'Park.' If the customer does not engage the parking brake, potential for movement of the vehicle increases the risk of injury or crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : There is no preceding warning.

**Involved Components :**

Component Name 1 : CASE-AUTO TRANS

Component Description : Automatic Transmission

Component Part Number : 31311 X280A

**Supplier Identification :****Component Manufacturer**

Name : JATCO

Address : 1974 Midway Lane

Smyrna Tennessee 37167

Country : United States

**Chronology :**

See attached electronic Part 573 for chronology

## Description of Remedy :

Description of Remedy Program : A remedy plan for all affected vehicles is currently under development.

When the final remedy plan is available, Nissan will mail final remedy notification letters and include a statement concerning reimbursement for the cost of obtaining a pre-notification remedy for a subject vehicle that was no longer under warranty at the time of a repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/ When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Dealers will be notified on July 8, 2022. Nissan will mail interim notification letters to all affected owners beginning July 20, 2022, advising them to apply the parking brake whenever they park their vehicle.

Planned Dealer Notification Date : JUL 08, 2022 - NR

Planned Owner Notification Date : JUL 20, 2022 - NR

\* NR - Not Reported